Easy implant removal









· Excellent cutting performance of SR drill

· Simple and quick removal in step 2


· Removal success rate over 90%






SR Tip

Variety of Cases Possible for Prostheses Fails




Screw fracture





Abutment fracture






Screw hex slip



AR tip (mini)



Internal thread crushing burden Re-tap