
TSIII ø5.5 Implant




Specification of ø5.5 Fixture



Indication of ø5.5 Fixture

1. To overcome Poor Initial Fixation of Ø5.0 Fixture : Replace 5.0 Fixture with 5.5 Fixture when the initial fixation is weak



2. Immediate Replacement for Failed Ø4.5 Fixture : When Ø4.5 Fixture failed and bone quality is weak, Ø5.5 Fixture is a good alternative for the position

Failure of of ø4.5 Fixture

OSSTEM Fixture Line-up
5.5 New


03.0
03.5
04.0
04.5
05.0
06.0
07.0

Ts
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
J
<t

3. Not enough Ridge for Ultra-Wide Fixture : When there is adjacent teeth or not enough ridge for Ultra-Wide fixture, Ø5.5 will be selected rather than Ø6.0







DEUTSCHE OSSTEM GmbH

SSTE

IMPLANT

Mergenthalerallee 25, 65760 Eschborn, Germany Tel: +49(0)6196 777 550 Fax: +49(0)6196 777 5529 E-mail: info@osstem.de www.osstem.de